#### **DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

## WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-004147 Address: 333 Burma Road **Date Inspected:** 24-Sep-2008

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1730 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** Jeff Chen **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component:** OBG and Tower

### **Summary of Items Observed:**

On this date, Caltrans Office of Structure Materials (OSM) Quality Assurance Inspector (QA) Raymond Lara was present at jobsite in Zhenhua Port Machinery Company facility on Changxing Island, China for the purpose of observing and monitoring the fabrication of the Tower and OBG.

### Bay Sub-Assembly

The Quality Assurance Inspector performed Ultrasonic Testing (UT), prescreening, on completed Partial Joint Penetration (PJP) groove welds, tack weld areas only, on Deck Panel DP037-001. The prescreening is in effort to determine the condition of said tack welds for compliance with project specifications. Numerous indications indicative of cracks were located and the data was forwarded to structural materials representative Peter Dautermann for future review.

### Tower Mock UP Area

The Quality Assurance Inspector observed ZPMC personnel perform magentic particle inspection on the fit up area of the 89 meter fit lug mock up. ZPMC personnel informed the Quality Assurance Inspector not indications were discovered in the base metal and are ready to fit the lug onto the fit up area. The Quality Assurance Inspector for informational pruposes only performed a random magnetic particle test on the base metal. The fit up area appeared to by free of indications.

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)



# **Summary of Conversations:**

No relevant conversations on this date.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Ady Velasco 138-1694-2685, who represents the Office of Structural Materials for your project.

<b>Inspected By:</b>	Lara,Raymond	Quality Assurance Inspector
Reviewed By:	Lanz,Joe	QA Reviewer